

David Myers Soil Consultants, LLC
PO Box 5088, Cleveland, TN 37320
423-716-2577
davidmyers@dmsoil.com

HIGH INTENSITY SOIL MAP

County: Bradley

Date: 10/13/2025


Client: Wilma Cross

Site Location: Candies Creek Ridge Road


Soil Name and Depths (inches)	Estimated Absorption Rate (mpi)	Depth to Restricting Layer (inches)	Soil Notes, Improvement Practices, Percolation Status
<i>Fullerton 0-48</i>	<i>60</i>	<i>>48</i>	

Notes:


1. This soil report is an accurate High Intensity soil evaluation in accordance with TDEC standards.
2. Soil auger locations shown on this map were plotted by use of a Global Positioning System (Trimble).
3. **Any cutting, filling, or compaction will void this soil map.**
4. Signature of the soil consultant does not constitute approval of this soil map by the Division of Water Resources.
5. This soil map is to evaluate the site for a subsurface sewage disposal system only. This soil map complies with the standards established in the TN Onsite Wastewater Manual, the Soil Survey Manual, and the Soil Taxonomy. No other warranties are made or implied.
6. The information contained in this report is based on the professional opinion and judgment of David Myers Soil Consultants, LLC. The soil scientist has no control over the permitting, design, installation, or maintenance of septic systems. Therefore, the soil scientist does not guarantee the performance of any septic system installed on this property.



LOCATION MAP



SOILS LEGEND & SLOPE CLASSES: Fullerton, 5-15%



High Intensity Soil Map
October 13, 2025